

Eastern Counties Omnibus Company - LL class vehicles

| Fleet No (Orig) | Fleet No (Subsequent) | Reg'n No | Chassis No | Body No | Chassis Designation | Body Designation | Year New | Year Renumbered | Year Withdrawn | Subsequent Owners |
|--------------------|--------------------------|----------|------------|----------------|------------------------|---------------------|----------|--------------------|-------------------|-------------------|
| LL 1 | LL 501 | CNG 201 | 43.90 | E.C.W. 5131 | L4G | DP32R | 1938 | 1946/7 | 1950 | |
| LL 2 | LL 502 | CNG 202 | 43.91 | E.C.W. 5132 | L4G | DP32R | 1938 | 1946/7 | 1952 | |
| LL 3 | LL 503 | CNG 203 | 43.92 | E.C.W. 5133 | L4G | DP32R | 1938 | 1946/7 | 1952 | |
| LL 4 | LL 504 | CNG 204 | 43.93 | E.C.W. 5134 | L4G | DP32R | 1938 | 1946/7 | 1951 | |
| LL 5 | LL 505 | CNG 205 | 43.94 | E.C.W. 5135 | L4G | DP32R | 1938 | 1946/7 | 1952 | |
| LL 6 | LL 506 | CNG 206 | 43.95 | E.C.W. 5136 | L4G | DP32R | 1938 | 1946/7 | 1951 | |
| LL 7 | LL 507 | CNG 207 | 43.96 | E.C.W. 5137 | L4G | DP32R | 1938 | 1946/7 | 1952 | |
| LL 8 | LL 508 | CNG 208 | 43.97 | E.C.W. 5138 | L4G | DP32R | 1938 | 1946/7 | 1952 | |
| LL 9 | LL 509 | CNG 209 | 43.98 | E.C.W. 5139 | L4G | DP32R | 1938 | 1946/7 | 1952 | |
| LL 10 | LL 510 | CNG 210 | 43.99 | E.C.W. 5140 | L4G | DP32R | 1938 | 1946/7 | 1952 | |
| LL 11 | LL 511 | CNG 211 | 43.100 | E.C.W. 5141 | L4G | DP32R | 1938 | 1946/7 | 1953 | |
| LL 12 | LL 512 | CNG 212 | 44.1 | E.C.W. 5142 | L4G | DP32R | 1938 | 1946/7 | 1951 | |
| LL 13 | LL 513 | CNG 213 | 44.3 | E.C.W. 5143 | L4G | B35R | 1938 | 1946/7 | 1952 | |
| LL 14 | LL 514 | CNG 214 | 44.4 | E.C.W. 5144 | L4G | B35R | 1938 | 1946/7 | 1952 | |
| LL 15 | LL 515 | CNG 215 | 44.5 | E.C.W. 5145 | L4G | B35R | 1938 | 1946/7 | 1952 | |
| LL 16 | LL 516 | CNG 216 | 44.2 | E.C.W. 5146 | L4G | B35R | 1938 | 1946/7 | 1952 | |
| LL 17 | LL 517 | CNG 217 | 44.6 | E.C.W. 5147 | L4G | B35R | 1938 | 1946/7 | 1952 | |

Eastern Counties Omnibus Company - LL class vehicles

| | | | | | | | | | |
|-------|--------|---------|-------|----------------|-----|------|------|--------|------|
| LL 18 | LL 518 | CNG 218 | 44.7 | E.C.W. 5148 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 19 | LL 519 | CNG 219 | 44.8 | E.C.W. 5149 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 20 | LL 520 | CNG 220 | 44.9 | E.C.W. 5150 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 21 | LL 521 | CNG 221 | 44.10 | E.C.W. 5151 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 22 | LL 522 | CNG 222 | 44.11 | E.C.W. 5152 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 23 | LL 523 | CNG 223 | 44.12 | E.C.W. 5153 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 24 | LL 524 | CNG 224 | 44.13 | E.C.W. 5154 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 25 | LL 525 | CNG 225 | 44.14 | E.C.W. 5155 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 26 | LL 526 | CNG 226 | 44.15 | E.C.W. 5156 | L4G | B35R | 1938 | 1946/7 | 1956 |
| LL 27 | LL 527 | CNG 227 | 44.16 | E.C.W. 5157 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 28 | LL 528 | CNG 228 | 44.17 | E.C.W. 5158 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 29 | LL 529 | CNG 229 | 44.18 | E.C.W. 5159 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 30 | LL 530 | CNG 230 | 44.19 | E.C.W. 5160 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 31 | LL 531 | CNG 231 | 44.20 | E.C.W. 5161 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 32 | LL 532 | CNG 232 | 44.21 | E.C.W. 5162 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 33 | LL 533 | CNG 233 | 44.22 | E.C.W. 5163 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 34 | LL 534 | CNG 234 | 44.23 | E.C.W. 5164 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 35 | LL 535 | CNG 235 | 44.24 | E.C.W. 5165 | L4G | B35R | 1938 | 1946/7 | 1952 |

Eastern Counties Omnibus Company - LL class vehicles

| | | | | | | | | | |
|-------|--------|---------|-------|----------------|-----|------|------|--------|------|
| LL 36 | LL 536 | CNG 236 | 44.25 | E.C.W. 5166 | L4G | B35R | 1938 | 1946/7 | 1952 |
| LL 37 | LL 537 | CVF 837 | 48003 | 6244 | L5G | B35R | 1939 | 1946/7 | 1952 |
| LL 38 | LL 538 | CVF 838 | 48004 | 6245 | L5G | B35R | 1939 | 1946/7 | 1953 |
| LL 39 | LL 539 | CVF 839 | 48005 | 6246 | L5G | B35R | 1939 | 1946/7 | 1953 |
| LL 40 | LL 540 | CVF 840 | 48006 | 6243 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 41 | LL 541 | CVF 841 | 48007 | 6247 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 42 | LL 542 | CVF 842 | 48048 | 6248 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 43 | LL 543 | CVF 843 | 48049 | 6249 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 44 | LL 544 | CVF 844 | 48050 | 6250 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 45 | LL 545 | CVF 845 | 48051 | 6251 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 46 | LL 546 | CVF 846 | 48052 | 6252 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 47 | LL 547 | CVF 847 | 48053 | 6253 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 48 | LL 548 | CVF 848 | 48054 | 6260 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 49 | LL 549 | CVF 849 | 48055 | 6254 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 50 | LL 550 | CVF 850 | 48056 | 6255 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 51 | LL 551 | CVF 851 | 48057 | 6273 | L5G | B35R | 1939 | 1946/7 | 1959 |
| LL 52 | LL 552 | CVF 852 | 48121 | 6265 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 53 | LL 553 | CVF 853 | 48122 | 6256 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 54 | LL 554 | CVF 854 | 48123 | 6257 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 55 | LL 555 | CVF 855 | 48124 | 6258 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 56 | LL 556 | CVF 856 | 48125 | 6259 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 57 | LL 557 | CVF 857 | 48126 | 6261 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 58 | LL 558 | CVF 858 | 48191 | 6266 | L5G | B35R | 1939 | 1946/7 | 1956 |
| LL 59 | LL 559 | CVF 859 | 48192 | 6267 | L5G | B35R | 1939 | 1946/7 | 1956 |
| LL 60 | LL 560 | CVF 860 | 48193 | 6262 | L5G | B35R | 1939 | 1946/7 | 1956 |
| LL 61 | LL 561 | CVF 861 | 48194 | 6268 | L5G | B35R | 1939 | 1946/7 | 1957 |
| LL 62 | LL 562 | CVF 862 | 48195 | 6269 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 63 | LL 563 | CVF 863 | 48196 | 6263 | L5G | B35R | 1939 | 1946/7 | 1957 |
| LL 64 | LL 564 | CVF 864 | 48197 | 6270 | L5G | B35R | 1939 | 1946/7 | 1956 |
| LL 65 | LL 565 | CVF 865 | 48198 | 6264 | L5G | B35R | 1939 | 1946/7 | 1957 |
| LL 66 | LL 566 | CVF 866 | 48199 | 6271 | L5G | B35R | 1939 | 1946/7 | 1956 |
| LL 67 | LL 567 | CVF 867 | 48200 | 6272 | L5G | B35R | 1939 | 1946/7 | 1956 |
| LL 68 | LL 568 | CVF 868 | 50016 | 6274 | L5G | B35R | 1939 | 1946/7 | 1957 |
| LL 69 | LL 569 | CVF 869 | 50017 | 6275 | L5G | B35R | 1939 | 1946/7 | 1958 |
| LL 70 | LL 570 | CVF 870 | 50018 | 6276 | L5G | B35R | 1939 | 1946/7 | 1957 |
| LL 71 | LL 571 | CVF 871 | 50019 | 6277 | L5G | B35R | 1939 | 1946/7 | 1956 |

Eastern Counties Omnibus Company - LL class vehicles

| | | | | | | | | | |
|--------|--------|---------|-------|------|-----|-------|------|--------|------|
| LL 72 | LL 572 | CVF 872 | 50020 | 6278 | L5G | B35R | 1939 | 1946/7 | 1956 |
| LL 73 | LL 573 | CVF 873 | 50021 | 6279 | L5G | B35R | 1939 | 1946/7 | 1954 |
| LL 74 | LL 574 | CVF 874 | 50022 | 6280 | L5G | B35R | 1939 | 1946/7 | 1957 |
| LL 75 | LL 575 | CVF 875 | 50023 | 6285 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 76 | LL 576 | CVF 876 | 50024 | 6281 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 77 | LL 577 | CVF 877 | 50025 | 6282 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 78 | LL 578 | CVF 878 | 50026 | 6283 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 79 | LL 579 | CVF 879 | 50027 | 6284 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 80 | LL 580 | CVF 880 | 50028 | 6286 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 81 | LL 581 | CVF 881 | 50029 | 6287 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 82 | LL 582 | CVF 882 | 50030 | 6288 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 83 | LL 583 | CVF 883 | 50031 | 6289 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 84 | LL 584 | CVF 884 | 50032 | 6290 | L5G | DP32R | 1939 | 1946/7 | 1954 |
| LL 85 | LL 585 | EAH 685 | 54041 | 6876 | L5G | B35R | 1941 | 1946/7 | 1959 |
| LL 86 | LL 586 | EAH 686 | 54038 | 6877 | L5G | B35R | 1941 | 1946/7 | 1959 |
| LL 87 | LL 587 | EAH 787 | 54066 | 6878 | L5G | B35R | 1941 | 1946/7 | 1956 |
| LL 88 | LL 588 | EAH 788 | 54068 | 6879 | L5G | B35R | 1941 | 1946/7 | 1956 |
| LL 89 | LL 589 | EAH 789 | 54064 | 6880 | L5G | B35R | 1941 | 1946/7 | 1956 |
| LL 90 | LL 590 | EAH 890 | 54042 | 6881 | L5G | B35R | 1942 | 1946/7 | 1956 |
| LL 91 | LL 591 | EAH 891 | 54074 | 6882 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 92 | LL 592 | EAH 892 | 54056 | 6883 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 93 | LL 593 | EAH 893 | 54032 | 6884 | L5G | B35R | 1942 | 1946/7 | 1957 |
| LL 94 | LL 594 | EAH 894 | 54049 | 6885 | L5G | B35R | 1942 | 1946/7 | 1957 |
| LL 95 | LL 595 | ENG 345 | 54069 | 6886 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 96 | LL 596 | ENG 346 | 54048 | 6887 | L5G | B35R | 1942 | 1946/7 | 1957 |
| LL 97 | LL 597 | ENG 347 | 54073 | 6888 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 98 | LL 598 | ENG 348 | 54062 | 6889 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 99 | LL 599 | ENG 349 | 54033 | 6890 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 100 | LL 600 | ENG 640 | 54034 | 6891 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 101 | LL 601 | ENG 641 | 54040 | 6892 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 102 | LL 602 | ENG 642 | 54054 | 6893 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 103 | LL 603 | ENG 643 | 54035 | 6894 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 104 | LL 604 | ENG 644 | 54059 | 6895 | L5G | B35R | 1942 | 1946/7 | 1956 |
| LL 105 | LL 605 | ENG 705 | 54055 | 6896 | L5G | B35R | 1942 | 1946/7 | 1957 |
| LL 106 | LL 606 | ENG 706 | 54030 | 6897 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 107 | LL 607 | ENG 707 | 54043 | 6898 | L5G | B35R | 1942 | 1946/7 | 1959 |

Eastern Counties Omnibus Company - LL class vehicles

| | | | | | | | | | |
|--------|--------|---------|-------|------|-----|------|------|--------|------|
| LL 108 | LL 608 | ENG 708 | 54063 | 6899 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 109 | LL 609 | ENG 709 | 54050 | 6900 | L5G | B35R | 1942 | 1946/7 | 1957 |
| LL 110 | LL 610 | ENG 220 | 54067 | 6901 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 111 | LL 611 | ENG 221 | 54072 | 6902 | L5G | B35R | 1942 | 1946/7 | 1957 |
| LL 112 | LL 612 | ENG 222 | 54031 | 6903 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 113 | LL 613 | ENG 223 | 54046 | 6904 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 114 | LL 614 | ENG 224 | 54060 | 6905 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 115 | LL 615 | ENG 355 | 54052 | 6906 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 116 | LL 616 | ENG 356 | 54057 | 6907 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 117 | LL 617 | ENG 357 | 54065 | 6908 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 118 | LL 618 | ENG 358 | 54061 | 6909 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 119 | LL 619 | ENG 359 | 54036 | 6910 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 120 | LL 620 | ENG 720 | 54053 | 6911 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 121 | LL 621 | ENG 721 | 54070 | 6912 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 122 | LL 622 | ENG 722 | 54058 | 6913 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 123 | LL 623 | ENG 723 | 54071 | 6914 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 124 | LL 624 | ENG 724 | 54047 | 6915 | L5G | B35R | 1942 | 1946/7 | 1959 |
| LL 125 | LL 625 | ENG 725 | 54044 | 6916 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 126 | LL 626 | ENG 726 | 54039 | 6917 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 127 | LL 627 | ENG 727 | 54051 | 6918 | L5G | B35R | 1942 | 1946/7 | 1957 |
| LL 128 | LL 628 | ENG 728 | 54045 | 6919 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 129 | LL 629 | ENG 729 | 54037 | 6920 | L5G | B35R | 1942 | 1946/7 | 1958 |
| LL 130 | LL 630 | FPW 501 | W4047 | 1075 | L5G | B35R | 1946 | 1946/7 | 1961 |
| LL 131 | LL 631 | FPW 502 | W4048 | 1076 | L5G | B35R | 1946 | 1946/7 | 1962 |
| LL 132 | LL 632 | FPW 503 | 61019 | 1237 | L5G | B35R | 1946 | 1946/7 | 1961 |
| LL 133 | LL 633 | FPW 504 | 61061 | 1257 | L5G | B35R | 1946 | 1946/7 | 1962 |
| LL 134 | LL 634 | FPW 505 | 61062 | 1258 | L5G | B35R | 1946 | 1946/7 | 1962 |
| LL 135 | LL 635 | FPW 506 | 61063 | 1259 | L5G | B35R | 1946 | 1946/7 | 1962 |
| LL 136 | LL 636 | FPW 507 | 61074 | 1267 | L5G | B35R | 1947 | 1947 | 1963 |
| LL 137 | LL 637 | FPW 508 | 61075 | 1268 | L5G | B35R | 1947 | 1947 | 1963 |
| LL 638 | N/A | FPW 509 | 61120 | 1295 | L5G | B35R | 1947 | N/A | 1963 |
| LL 639 | N/A | FPW 510 | 61122 | 1296 | L5G | B35R | 1947 | N/A | 1963 |
| LL 640 | N/A | FPW 511 | 61121 | 1297 | L5G | B35R | 1947 | N/A | 1963 |
| LL 641 | N/A | FPW 512 | 61130 | 1315 | L5G | B35R | 1947 | N/A | 1963 |
| LL 642 | N/A | FPW 513 | 63004 | 1316 | L5G | B35R | 1947 | N/A | 1962 |
| LL 643 | N/A | FPW 514 | 63005 | 1317 | L5G | B35R | 1947 | N/A | 1962 |
| LL 644 | N/A | FPW 515 | 63021 | 1329 | L5G | B35R | 1947 | N/A | 1963 |

Eastern Counties Omnibus Company - LL class vehicles

| | | | | | | | | | |
|--------|-----|---------|-------|------|-----|------|------|-----|------|
| LL 645 | N/A | FPW 516 | 63022 | 1330 | L5G | B35R | 1947 | N/A | 1963 |
| LL 646 | N/A | FPW 517 | 63066 | 1358 | L5G | B35R | 1947 | N/A | 1962 |
| LL 647 | N/A | FPW 518 | 63067 | 1359 | L5G | B35R | 1947 | N/A | 1963 |
| LL 648 | N/A | FPW 519 | 63068 | 1360 | L5G | B35R | 1947 | N/A | 1963 |
| LL 649 | N/A | FPW 520 | 63102 | 1386 | L5G | B35R | 1947 | N/A | 1963 |
| LL 650 | N/A | FPW 521 | 63103 | 1387 | L5G | B35R | 1947 | N/A | 1963 |
| LL 651 | N/A | FPW 522 | 63114 | 1388 | L5G | B35R | 1947 | N/A | 1963 |
| LL 652 | N/A | FPW 523 | 63115 | 1394 | L5G | B35R | 1947 | N/A | 1963 |
| LL 653 | N/A | FPW 524 | 63195 | 1405 | L5G | B35R | 1947 | N/A | 1963 |
| LL 654 | N/A | FPW 525 | 63196 | 1406 | L5G | B35R | 1947 | N/A | 1964 |
| LL 655 | N/A | FPW 526 | 63197 | 1407 | L5G | B35R | 1947 | N/A | 1964 |
| LL 656 | N/A | FPW 527 | 63198 | 1408 | L5G | B35R | 1947 | N/A | 1964 |
| LL 657 | N/A | GPW 657 | 65099 | 1955 | L5G | B35R | 1948 | N/A | 1964 |
| LL 658 | N/A | GPW 658 | 65100 | 1956 | L5G | B35R | 1948 | N/A | 1964 |
| LL 659 | N/A | GPW 659 | 65134 | 1957 | L5G | B35R | 1948 | N/A | 1964 |
| LL 660 | N/A | GPW 660 | 65135 | 1958 | L5G | B35R | 1948 | N/A | 1964 |
| LL 661 | N/A | GPW 661 | 65136 | 1959 | L5G | B35R | 1948 | N/A | 1964 |
| LL 662 | N/A | GPW 662 | 65161 | 1960 | L5G | B35R | 1948 | N/A | 1964 |
| LL 663 | N/A | GPW 663 | 65162 | 1961 | L5G | B35R | 1948 | N/A | 1963 |
| LL 664 | N/A | GPW 664 | 65167 | 1962 | L5G | B35R | 1948 | N/A | 1965 |
| LL 665 | N/A | GPW 665 | 65168 | 1963 | L5G | B35R | 1948 | N/A | 1963 |
| LL 666 | N/A | GPW 666 | 65169 | 1964 | L5G | B35R | 1948 | N/A | 1965 |
| LL 667 | N/A | GPW 667 | 65175 | 1965 | L5G | B35R | 1948 | N/A | 1963 |
| LL 668 | N/A | GPW 668 | 65185 | 1966 | L5G | B35R | 1948 | N/A | 1963 |
| LL 669 | N/A | GPW 669 | 65186 | 1967 | L5G | B35R | 1948 | N/A | 1964 |
| LL 670 | N/A | GPW 670 | 67001 | 1968 | L5G | B35R | 1948 | N/A | 1964 |
| LL 671 | N/A | GPW 671 | 67002 | 1969 | L5G | B35R | 1948 | N/A | 1964 |
| LL 672 | N/A | GPW 672 | 67003 | 1970 | L5G | B35R | 1948 | N/A | 1964 |
| LL 673 | N/A | GPW 673 | 67009 | 1971 | L5G | B35R | 1948 | N/A | 1965 |
| LL 674 | N/A | GPW 674 | 67010 | 1972 | L5G | B35R | 1948 | N/A | 1966 |
| LL 675 | N/A | GPW 675 | 67026 | 1973 | L5G | B35R | 1948 | N/A | 1966 |
| LL 676 | N/A | GPW 676 | 67027 | 1974 | L5G | B35R | 1948 | N/A | 1964 |
| LL 677 | N/A | GPW 677 | 67028 | 1975 | L5G | B35R | 1948 | N/A | 1964 |
| LL 678 | N/A | GPW 678 | 67008 | 1976 | L5G | B35R | 1948 | N/A | 1965 |
| LL 679 | N/A | GPW 679 | 67050 | 1977 | L5G | B35R | 1948 | N/A | 1965 |
| LL 680 | N/A | GPW 680 | 67051 | 1978 | L5G | B35R | 1948 | N/A | 1965 |
| LL 681 | N/A | GPW 681 | 67052 | 1979 | L5G | B35R | 1948 | N/A | 1965 |

Eastern Counties Omnibus Company - LL class vehicles

| | | | | | | | | | |
|--------|--------|---------|--------|------|------|------|------|------|------|
| LL 682 | N/A | GPW 682 | 67100 | 1980 | L5G | B35R | 1948 | N/A | 1964 |
| LL 683 | N/A | GPW 683 | 67119 | 1981 | L5G | B35R | 1948 | N/A | 1965 |
| LL 684 | N/A | GPW 684 | 67117 | 1982 | L5G | B35R | 1948 | N/A | 1965 |
| LL 685 | N/A | GPW 685 | 67118 | 1983 | L5G | B35R | 1948 | N/A | 1965 |
| LL 686 | N/A | GPW 686 | 67107 | 1984 | L5G | B35R | 1948 | N/A | 1964 |
| LL 687 | N/A | GPW 687 | 67108 | 1985 | L5G | B35R | 1948 | N/A | 1965 |
| LL 688 | N/A | GPW 688 | 67111 | 1986 | L5G | B35R | 1948 | N/A | 1966 |
| LL 689 | N/A | GPW 689 | 67137 | 1987 | L5G | B35R | 1948 | N/A | 1966 |
| LL 690 | N/A | GPW 690 | 67138 | 1988 | L5G | B35R | 1948 | N/A | 1966 |
| LL 691 | N/A | GPW 691 | 67139 | 1989 | L5G | B35R | 1948 | N/A | 1966 |
| LL 692 | N/A | GPW 692 | 67140 | 1990 | L5G | B35R | 1948 | N/A | 1965 |
| LL 693 | N/A | GPW 693 | 67141 | 1991 | L5G | B35R | 1948 | N/A | 1966 |
| LL 694 | N/A | GPW 694 | 67155 | 1992 | L5G | B35R | 1948 | N/A | 1966 |
| LL 695 | N/A | GPW 695 | 67154 | 1993 | L5G | B35R | 1948 | N/A | 1965 |
| LL 696 | N/A | GPW 696 | 67153 | 1994 | L5G | B35R | 1948 | N/A | 1966 |
| LL 401 | LL 901 | KAH 401 | 73179R | 3402 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 402 | LL 902 | KAH 402 | 73180R | 3403 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 403 | LL 903 | KAH 403 | 73181R | 3404 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 404 | LL 904 | KAH 404 | 73182R | 3405 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 405 | LL 905 | KAH 405 | 73183R | 3406 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 406 | LL 906 | KAH 406 | 73184R | 3410 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 407 | LL 907 | KAH 407 | 73185R | 3407 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 408 | LL 908 | KAH 408 | 73186R | 3411 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 409 | LL 909 | KAH 409 | 73187R | 3408 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 410 | LL 910 | KAH 410 | 73188R | 3409 | L4G | B35R | 1949 | 1964 | 1965 |
| LL 709 | N/A | KNG 709 | 81008 | 4647 | L5G | B35R | 1950 | N/A | 1966 |
| LL 710 | N/A | KNG 710 | 81009 | 4648 | L5G | B35R | 1950 | N/A | 1966 |
| LL 711 | N/A | KNG 711 | 81010 | 4649 | L5G | B35R | 1950 | N/A | 1968 |
| LL 712 | N/A | KNG 712 | 81011 | 4650 | L5G | B35R | 1950 | N/A | 1967 |
| LL 713 | N/A | KNG 713 | 81102 | 4651 | LL5G | B39R | 1950 | N/A | 1967 |
| LL 714 | N/A | KNG 714 | 81103 | 4652 | LL5G | B39R | 1950 | N/A | 1966 |
| LL 715 | N/A | KNG 715 | 81104 | 4653 | LL5G | B39R | 1950 | N/A | 1967 |
| LL 716 | N/A | KNG 716 | 81105 | 4654 | LL5G | B39R | 1950 | N/A | 1968 |
| LL 717 | N/A | KNG 717 | 81175 | 4655 | LL5G | B39R | 1950 | N/A | 1967 |
| LL 718 | N/A | KNG 718 | 81176 | 4656 | LL5G | B39R | 1950 | N/A | 1967 |

Eastern Counties Omnibus Company - LL class vehicles

| | | | | | | | | | |
|--------|-----|---------|--------|------|-------|-------|------|-----|------|
| LL 719 | N/A | KNG 719 | 81177 | 4657 | LL5G | B39R | 1950 | N/A | 1966 |
| LL 720 | N/A | KNG 720 | 83031 | 4658 | LL5G | B39R | 1950 | N/A | 1967 |
| LL 721 | N/A | KNG 721 | 83032 | 4659 | LL5G | B39R | 1950 | N/A | 1967 |
| LL 722 | N/A | KNG 722 | 83033 | 4660 | LL5G | B39R | 1950 | N/A | 1968 |
| LL 723 | N/A | KNG 723 | 83034 | 4661 | LL5G | B39R | 1950 | N/A | 1967 |
| LL 724 | N/A | LNG 724 | 83035 | 4662 | LL5G | B39R | 1950 | N/A | 1967 |
| LL 725 | N/A | LNG 725 | 83145 | 4663 | LL5G | B39R | 1951 | N/A | 1967 |
| LL 726 | N/A | LNG 726 | 83146 | 4664 | LL5G | B39R | 1951 | N/A | 1967 |
| LL 727 | N/A | LNG 727 | 83152 | 4665 | LL5G | B39R | 1951 | N/A | 1967 |
| LL 728 | N/A | LNG 728 | 83153 | 4666 | LL5G | B39R | 1951 | N/A | 1967 |
| LL 729 | N/A | LNG 729 | 83237 | 4667 | LL5G | B39R8 | 1951 | N/A | 1968 |
| LL 730 | N/A | LNG 730 | 83238 | 4668 | LL5G | B39R8 | 1951 | N/A | 1967 |
| LL 731 | N/A | LNG 731 | 83239 | 4669 | LL5G | B39R8 | 1951 | N/A | 1967 |
| LL 732 | N/A | LNG 732 | 83243 | 5321 | LL5G | B39R8 | 1951 | N/A | 1967 |
| LL 733 | N/A | LNG 733 | 83244 | 5322 | LL5G | B39R8 | 1951 | N/A | 1968 |
| LL 734 | N/A | LNG 734 | 83245 | 5323 | LL5G | B39R8 | 1951 | N/A | 1967 |
| LL 735 | N/A | LNG 735 | 83246 | 5324 | LL5G | B39R8 | 1951 | N/A | 1968 |
| LL 736 | N/A | LNG 736 | 83247 | 5325 | LWL5G | B39R | 1951 | N/A | 1967 |
| LL 737 | N/A | LNG 737 | 83327 | 5326 | LWL5G | B39R | 1951 | N/A | 1968 |
| LL 738 | N/A | LNG 738 | 83328 | 5327 | LWL5G | B39R | 1951 | N/A | 1968 |
| LL 739 | N/A | LNG 739 | 83329 | 5328 | LWL5G | B39R | 1951 | N/A | 1968 |
| LL 740 | N/A | LNG 740 | 83330 | 5329 | LWL6B | B39R | 1951 | N/A | 1968 |
| LL 741 | N/A | LNG 741 | 85078 | 5330 | LWL6B | B39R | 1951 | N/A | 1968 |
| LL 742 | N/A | LNG 742 | 85079 | 5331 | LWL6B | B39R | 1951 | N/A | 1968 |
| LL 743 | N/A | LNG 743 | 85080 | 5332 | LWL6B | B39R | 1951 | N/A | 1968 |
| LL 744 | N/A | MAH 744 | LSX002 | 4255 | LS4G | B42F | 1951 | N/A | 1972 |